Figure 1-4 - Horsley Park Plant 2 Upgrade Environmental Status Report

SITE: Horsley Park Plant 2

Person(s) inspecting: Mal Mellows

SITE: Horsley Park Plant 2

Person(s) inspecting: Mai Mellows

Date: 28th Oct 2020

Person(s) consulted: Cassandra Steppachev.

			Issues or comments	Action Taker
INSPECTION ITEM	REFERENCE (and inspection details)	(Yes-	(Must complete if changes have occurred or non-compliance issues- Hazard must be opened for any issue or incident *see	
		N/A)	Hazard Reporting and Risk Control ~ SHE- MSP-All-06,001*	
GENERAL	Current progress of Construction / Demolition work	1	1001 941 941 941	meany (date)
	Have any changes occurred to Submitted Plans?	140		
	If so, should new checks be added or existing checks	1		
	modified?	NA		
	Any checks for new licence/permit/approval conditions be added to this list?	No		
	Has there been any Increased risk of hazard / fire?	No		
	Traffic Management - Is Traffic moving smoothly as designed?	YES		· · · · · · · · · · · · · · · · · · ·
DISPOSAL	SHE-MSP-Env-07.004			
	Have any hazardous substances been correctly disposed of?	NA		
	Have waste transport certificates been completed and retained on file?	YES	PLANT I BECOLDS,	
		Yes		
	Have any materials containing Asbestos been disturbed?	162 853	Romo wed as per Alca	
***************************************	Has it been handled according to Australian Standards? Has any Asbestos been disposed off?	₹ - 5		-
				
	Has it been disposed of to standard and have waste transport certificates been completed and retained on file?	YES		
OLLUTION	SHE-MSP-Env-07.332			
	Is all pollution control equipment operating correctly?	MA.		
	Is maintenance, emptying or replenishment required?	NA.		
	Are any additional pollution controls required?	No		
	SHE-MSP-Env-07.342			
	Are spill kits appropriately stocked and located?	YES		
	Are hydrocarbons stored correctly in bunds (or on bunded		Considuation	4
	pallets)?	NA,	HIL ON EUE.	
	Have all lids, caps, and bungs been refitted after use? Are empty hydrocarbon containers stored so as to not fill-up with rain?	75 0	<i>n</i> " " " " " " " " " " " " " " " " " " "	
WASTE	SHE-MSP-Env-07,334	* * ' ' '		
	Are initiatives to reduce waste functioning successfully?	P. J. Pre	MON OPERATIONAL SITE	
	Is any excess waste being generated?	140	MON OF SZATISON SITE	
	Is waste being separated for re-use or recycling where			
	possible?	YES	CEN WASTE STEEL.	
	Is re-usable or recyclable waste being stored appropriately?	NA	MON OPERATIONAL SO	Ē
	Are all bins, skips, bunkers and stockpiles clearly labelled?	<u>Y€S</u>	CIEN/SITEL WASTE	
- · - · · · · · · · · · · · · · · · · ·	is waste for disposal stored correctly and removed regularly?	YES_		
	SHE-MSP-Env-07.335			
	Have there been significant storms or rainfall events?	TES		
	Is stormwater flowing as designed?	<u> </u>		
	Are all drains and grates clear of blockages?	<u> </u>		
	Is surface water being correctly separated, directed and/or contained?	YES		
	Are all Erosion Sedimentation Controls in place& operating as required?	NA	NOT RECOILED ATTHIS	
			10. 100. 11 1103	SINC >
	Does pond, sump or surface water require treatment prior to	VD_		
	discharge?	YES_	QUARRY DAM	
	Are preventative measures being implemented to avoid poor water quality?	YES	WATER TREATMENT	
	House any application of the state of the st	YES	Through EPA PointI	
	Are all waste treatment or sewage (porta-loo) systems operating correctly?	YES		
	SHE-MSP-Env-10.335			
		4ES		
		100		

INSPECTION ITEM	REFERENCE (and Inspection details)	(Yes- No- N/A)	Issues or comments (Must complete if changes have occurred or non- compliance issues: Hazard must be opened for any issue or incident "see Hazard Reporting and Risk Control ~ SHE-MSP-AII-06.001"	Action Taken Eg. Hazard form (No.) OR Toolbox meeting (date)
LAND	SHE-MSP-Env-07.336			
	Has any Unexpected Contamination been discovered on site?	NO		
	If yes Has the contamination procedure been followed?	·		
	Has any Aboriginal Heritage been discovered? If yes Has the Aboriginal Heritage finds procedure been followed?	40		
	Is landscaping, re-vegetation or rehabilitation recommended?			
	Do fences and gates prevent vehicle/person/animal access as appropriate?	YES		
AIR	SHE-MSP-Env-07.321			
	Are existing dust suppression controls (sweeping/watercart/etc) effective?	Tes		
	Are raw materials stored to avoid becoming spilt and/or windblown?	YES		
	Are material transfer processes successful in minimising dust and spillage?	YES	77.770.770.770.770.770.770.770.770.770.	
	SHE-MSP-All-10.021 Are meteorological data & significant dust-creating activities recorded?	YES	Onsite Weather Static	n
	Is any dust potentially escaping off-site?	NO		
NOISE	SHE-MSP-Eny-07.322			
	Any work outside proscribed operating hours?	NO		
	SHE-MSP-AII-10.022			
	Are there are any potential off-site noise impacts?	170		
BULK LIQUID STORAGE	SHE-MSP-Eny-07.337 Are all liquid containers stored appropriately in suitable			
	locations? Are all above-ground tanks double-skinned or adequately	NA	NIL ONSITE	
	bunded? Are full IBC's stored in appropriate locations away from drains/waterways?	NO NO		
	Are damaged, faulty or dis-used IBC's being promptly removed from site?	MA.		
COMPLAINTS	SHE-MSP-Env-03.331	,		
& REPORTS	Have any complaints been recorded and investigated?	NIL		
	Have any incidents occurred?	NIL		l
	Have any incidents been reported to regulators as required?	NR		