

LICENSE REQUIREMENTS FOR WATER REQUIREMENTS

2 Discharges to Air and Water and Applications to Land

P1 Location of monitoring/discharge points and areas

P1.1 The following points referred to in the table below are identified in this licence for the purposes of monitoring and/or the setting of limits for the emission of pollutants to the air from the point.

<i>Air</i>			
EPA identification no.	Type of Monitoring Point	Type of Discharge Point	Location Description
4	Discharge to air; Air emissions monitoring	Discharge to air; Air emissions monitoring	Stack for Kiln Number 1 on Plant 1 as shown on drawing attached to Licence Information Form dated 24 September 1999
5	Discharge to air; Air emissions monitoring	Discharge to air; Air emissions monitoring	Stack for Kiln Number 5 at Plant 2 as shown on drawing attached to Licence Information Form dated 24 September 1999
6	Discharge to air; Air emissions monitoring	Discharge to air; Air emissions monitoring	Stack for Kiln number 6 on Plant 3 known as Swindle kiln as shown on drawing attached to Licence Information Form dated 24 September 1999
7	Discharge to air; Air emissions monitoring	Discharge to air; Air emissions monitoring	Stack for Kiln number 7 on Plant 3 known as Ceric kiln as shown on drawing attached to Licence Information Form dated 24 September 1999