

Table 1 – Road Distance and Responsibility

Road	Road Distance (km)	Travelled Distance From Mandurama Quarry Entrance (km)	Road Classification	Maintenance Responsibility	Maintenance Costs Funded By
Berrima Road	0.3	0.3	Local Road	Council	Council
Taylor Avenue	2.3	2.6	Regional Road	Council	Council/RTA (Funds determined by submission to RTA)
Medway Road	1.2	3.8	Regional Road	Council	Council/RTA (Funds determined by submission to RTA)
Hume Highway	12.3	16.1	State Road	RTA	RTA
Old Hume Highway	2.0	18.1	Regional Road	Council	Council/RTA (Funds determined by submission to RTA)
Cavendish Street	0.8	18.9	Local Road	Council	Council
Old Bowral Road	0.1	19.0	Local Road	Council	Council
Mittagong Road (The Highlands Way/Bowral Road)	2.1	21.1	Regional Road	Council	Council/RTA (Funds determined by submission to RTA)
Lyle Avenue	0.7	21.8	Local Road	Council	Council
Kirkham Road	1.4	23.2	Local Road	Council	Council
Oxley Hills Road	0.3	23.5	Local Road	Council	Council
Kiama Street	0.2	23.7	Local Road	Council	Council