

Cardup Stakeholder Community Group

Presentation – July 2021



Operations Update

Southern Pit:
Shale Road Annual Report 2020-2021
submitted and available on website.

Cardup Plant:
Steady state operations.
DWER inspection in April. Deemed compliant.
EPA Assessment ongoing.



Map 1: Premises Map. The boundary of the premises is shown in red




Map 2: Manufacturing area layout.



Cardup - Asphalt





Northern Pit (inactive)

Update:

- Mulch applied to top end of pit.

